

# REPORT

DATE ISSUED: September 30, 2009

REPORT NO.:HCR09-101

ATTENTION:

Chair and Members of the Housing Commission

For the Agenda of October 16, 2009

SUBJECT:

Modification of Loan to City Heights Community Development Corporation

(CHCDC)

(Council Districts 3 and 7)

### REQUESTED ACTION:

Housing Commission approval of modifications to previously approved loans to the CHCDC and the associated rent restrictions.

#### STAFF RECOMMENDATION:

Housing Commission approval of the following measures:

- (1) Approve decreasing the previously approved (aggregated) amortizing loan to CHCDC, to a total loan of \$2,389,467 (which would be split into individual loans on each of five properties as detailed in Attachments 1 and 2, and as further described in item (2) of this recommendation), of which \$1,789,467 would be amortized and \$600,000 would be residual.
- (2) Approve uses of \$600,000 requested by CHCDC for additional energy efficiency as follows:

Additional energy efficiency hard costs	\$442,257
Addition to relocation budget	100,823
Addition to Hard/Soft cost contingency*	<u>56,920</u>
Total Approved Additional Uses of Funds	\$600,000

<sup>\*</sup>Unused Hard/Soft contingency up to \$30,000 may be added to developer fee.

- (3) Approve modifying pre-existing SDHC loans (subordinate to rehab loans) at Canyon Vista, Euclid Court, San Diego Apartments, and Teralta, from 100% of residual receipts to 50% of residual receipts.
- (4) Approve, as a condition of the foregoing approvals, the requirement that 35% AMI rent restrictions be phased out over a ten year period after completion of rehabilitation, at the rate of at least 10% of the 60 total project units (i.e. six units) per year, so that all 60 rehabilitated units will eventually be rent restricted at 50% AMI and 60% AMI.

Date Issued: September 30, 2009 Modification of Loan to City Heights CDC Page 2

## BACKGROUND:

On June 1, 2009, the City Council approved the Community Development Block Grant — Recovery (CDBG-R) Program, which included a grant allocation of \$684,000 for two of the five CHCDC rehab projects as follow: San Diego Apartments (\$266,000) and the Euclid Court Apartments (\$418,000), and as shown in Attachment 1 (CHCDC Sources and Uses of Funds). CDBG-R Program funds have not yet been funded by the City of San Diego, however, and CDBG-R funded costs at San Diego Apartments and at Euclid Court cannot be incurred against these CDBG-R allocations until a contract for the funds has been executed by the City.

On June 19, 2009, the Housing Commission approved a total loan amount of up to \$2,473,467 for the rehabilitation of 60 units of low-income apartments located at five separate CHCDC properties in City Heights, with the expectation that when the \$684,000 of CDBG-R funds were received for San Diego Apartments and Euclid Court, the total amount of the Housing Commission loan was to be reduced by \$684,000 to \$1,789,467.

On July 14, 2009 the Housing Authority approved the rehabilitation loan. In a motion by Councilperson Gloria, the Housing Commission was authorized to make an amortizing loan of up to \$2,473,467, however, once CDBG-R funds were received for the rehabilitation of two of the five properties, the total amortizing loan amount could be reduced to \$1,789,467, and the resulting savings of \$684,000 of Housing Commission funds could then be utilized for additional energy efficiency and sustainability improvements at all five properties and funded by the Housing Commission as 3% residual receipts loans.

### DISCUSSION

Pursuant to the Housing Commission and Housing Authority board approvals, the Housing Commission and CHCDC entered into five (5) sets of loan documents dated July 29, 2009. If the recommendations included in this report are approved, the various loan amounts will be reallocated as set forth in Attachment 1 (CHCDC Sources and Uses of Funds) and in Attachment 2 (CHCDC Comprehensive Scopes of Work).

The previously approved rehabilitation loan was based on a scope of work that included landscaping, site drainage, walkway repairs, kitchen and bathroom remodeling, roofing and insulation, energy efficient door and window replacements, ceiling fans, floor coverings, interior and exterior painting, appliances, water-efficient plumbing fixtures, retrofitting of five percent of the units for accessibility, and lead abatement at two properties (Canyon Vista and Euclid Court) built in the 1940's.

At both the Housing Commission and Housing Authority meetings, there was discussion and encouragement for additional energy efficiency and sustainability scope of work, if funding were available. CHCDC is now asking to increase the original rehabilitation budget by \$600,000 to add energy efficiency and sustainability hard costs and for additional soft costs.

Date Issued: September 30, 2009

Modification of Loan to City Heights CDC

Page 3

The additional rehab scope of work focuses on "green" upgrades in carpeting, roofing, lighting, and insulation. Many units will require additional relocation during the rehabilitation period for energy efficiency, fumigation, lead abatement, kitchen or bath remodels, and carpet installation. Additional relocation funds are included in the \$600,000 budget request.

Attachment 2 summarizes, by property and by line item, the Rehab Scope of Work already approved for funding and the revised Rehab Scope of Work being requested by CHCDC.

SDHC staff has reviewed CHCDC's Scope of Work revisions and concomitant budget revisions for hard costs and soft costs for each of the five properties in making this recommendation.

The recommended decrease in the SDHC loan amount to \$2,389,467, combined with the \$684,000 CDBG-R grant from the City, will provide total sources of funds of \$3,073,467 to balance CHCDC's total uses of funds of \$3,073,467 for the RE-5 project.

### AFFORDABLE HOUSING IMPACT:

The Housing Commission has already recorded 55-year rent restrictions against these properties. Rents are currently affordable and will remain affordable to tenants with annual incomes of 35 percent or less of Area Median Income (currently \$28,900 for a four-person household) for 16 units, for tenants with annual incomes of 50 percent or less of AMI (currently \$41,300 for a four-person household) for 14 units, and for tenants with annual incomes of 60 percent or less of AMI (currently \$49,560 for a four-person household) for 30 units.

There is one rent-restricted, on-site property manager's unit at the 16-unit San Diego Apartments.

#### FINANCING:

The recently approved \$2,473,467 SDHC funding (\$41,225 per unit) for rehabilitation is already documented by a second position 55 year, 3% amortized loans recorded against each of the five properties. The loan amounts are based on previously approved hard costs and a percentage of the aggregated soft cost costs and pro rated reserves based on the number of units at each site. These five loan agreements must to be modified to reflect the revised scopes of work. The revised loan amount reduces SDHC's rehab funding to \$39,824 per unit over the 60 project units.

For the purpose of repayment, each Housing Commission rehab loan would be subordinate to current first lien position financing of each property. The developer-provided proformas indicate the properties will be able to sustain the anticipated debt service of the first position loan and proposed amortized second position rehab loans as modified, with remaining cash flow available to pay residual receipts being minimal (initially about \$14,000 annually).

Date Issued: September 30, 2009

Modification of Loan to City Heights CDC

Page 4

SDHC made loans to CHCDC on four of the five rehab properties during the 1990s, as follow:

1992	San Diego Apartme	nts\$220,000	3% interest	55 year amortizing	100% res rec
1993	Euclid Court	\$273,939	3% interest	55 year amortizing	100% res rec
1995	Teralta	\$236,557	3% interest	55 year amortizing	100% res rec
1997	Canyon Vista	\$135,627	3% interest	55 year amortizing	100% res rec

These earlier SDHC loans at four of five CHCDC rehab properties are subordinate to the SDHC rehab loans. CHCDC is requesting that these four SDHC loan agreements be modified from 100% residual receipts after payment of the first-priority (bank) and second-priority (SDHC rehab) loans to 50% residual receipts after higher priority debt service, so that CHCDC will have an opportunity to receive some portion of future cash flows for its own operations. These loan modifications are recommended by staff as part of this Housing Commission approval.

Staff recommends placing a "phasing out" requirement on CHCDC to gradually eliminate 35% AMI units from this 60 unit project inventory. Rents below 50% AMI have proven to be a constraint against a property being able to cover operating costs, reserves, and debt service over the long term. The gradual elimination of 35% AMI rent restrictions will still give the borrower the option, but not the obligation, to use lower rents, but only if operating costs, reserves, and debt service can be covered. Rent restrictions at 50% AMI comply with all of the requirements of our major funding sources.

### AFFORDABLE HOUSING IMPACT:

The Housing Commission has already recorded 55-year rent restrictions against these properties. Rents are currently affordable and will remain affordable to tenants with annual incomes of 35 percent or less of Area Median Income (currently \$28,900 for a four-person household) for 16 units, for tenants with annual incomes of 50 percent or less of AMI (currently \$41,300 for a four-person household) for 14 units, and for tenants with annual incomes of 60 percent or less of AMI (currently \$49,560 for a four-person household) for 30 units.

## **PREVIOUS ACTIONS:**

On June 1, 2009, the City Council approved the Community Development Block Grant — Recovery (CDBG-R) Program Substantial Amendment which included the approval of the financing of rehabilitation hard construction costs for the San Diego Apartments (\$266,000) and the Euclid Court Apartments (\$418,000).

On June 19, 2009, the Housing Commission approved the existing total SDHC loan amount of \$2,473,467 with the following conditions: (a) the borrower must maintain a minimum capitalized reserve account of \$108,000; (b) annual deposits to the reserve accounts will be made at \$350 per unit; and, (c) the borrower must submit a quarterly operations report to the Housing Commission.

Date Issued: September 30, 2009

Modification of Loan to City Heights CDC

Page 5

On July 14, the Housing Authority approved the SDHC loan amount of up to \$2,473,467, as approved by the Housing Commission, with an additional approval of a floor motion to approve \$1,789,467 of the amount as a 3%, 55 year amortizing loan, with the remaining loan amount being residual receipts.

## **COMMUNITY PARTICIPATION AND PUBLIC OUTREACH EFFORTS:**

The initially proposed development received a positive vote of support by the City Heights Planning Area Committee at its regular meeting on July 21, 2008. The group voted with 14 in favor, one opposed, and two abstentions to support the acquisition/rehabilitation project.

## **KEY STAKEHOLDERS & PROJECTED IMPACTS:**

The current owner is the City Heights Community Development Corporation (CHCDC), a California nonprofit public benefit corporation. Stakeholders include CHCDC as the nonprofit owner, manager and developer and the community of City Heights. The project is expected to have a positive impact on the community because it will contribute to the quality of the surrounding neighborhood and increase the life of this much-needed rental housing affordable to low-income individuals and families by rehabilitating and preserving the affordability of 60 rental units for 55 years.

### **ENVIRONMENTAL REVIEW:**

Each of the five rehabilitation projects encompassing the action discussed above is exempt from the California Environmental Quality Act (CEQA) pursuant to State CEQA guidelines 15301 (existing facilities). The proposed activities are also determined to be Categorically Excluded pursuant to 24 CFR 58.35(a)(3) under the National Environmental Policy Act.

Submitted by,

D. Lawrence Clemens Senior Vice President Approved by,

for: CarroLM. Vaughan

Executive Vice President & Chief Operating Officer

Date Issued: September 30, 2009 Modification of Loan to City Heights CDC Page 6

Attachments:

- 1. CHCDC RE-5 Sources and Uses of Funds
- 2. CHCDC "Comprehensive Scopes of Work"

A copy is available for review at the Housing Commission offices located at 1122 Broadway, Suite 300 and at the offices of the City Clerk located on the 2<sup>nd</sup> floor of 202 "C" Street.

Information: J. Lohla (619) 578-7595

City Heights Community Development Corporation RE-5 Rehabilitation	pment Corpora	ation RE-5 Re	shabilitation									
Sources and Uses of Funds												
	Teralta - 13 units	3 units	Alta Vista -	12 units	Canyon Vista	- 8 units	San Diego - 16 units	16 units	Euclid Court - 11 units	. 11 units	Current Sources	Revised Sources
Current Hard Cost	\$ 387,635		\$ 471,243		\$ 309,881		\$ 253,708		\$ 453,764		\$ 1,876,231	
Revised Hard Cost		\$ 443,204		\$ 531,732		\$ 459,223		\$ 291,908		\$ 592,421		\$ 2,318,488
Current Soft Cost	\$ 129,401		\$ 119,447		\$ 79,631	-1/1/ /// /// ///	\$ 159,263		\$ 109,493		\$ 597,235	
Revised Saft Cast	_	\$ 163,579	_	\$ 150,996		\$ 100,664		\$ 201,328	-	\$ 138,413		\$ 754,980
Current Total Cost	\$ 517,036		069'065 \$		\$ 389,513		\$ 412,971		\$ 563,257		\$ 2,473,467	
Revised Total Cost		\$ 606,783		\$ 682,728		\$ 559,887		\$ 493,236	-	\$ 730,834		\$ 3,073,468
Current SDHC Loan Amount	\$ \$17,036		069'065 \$		\$ 389,513		\$ 412,971		\$ 563,257		\$ 2,473,467	
Revised SDHC Loan Amount	-	\$ 606,783	_	\$ 682,728		\$ 559,886		\$ 227,236	-	\$ 312,834 Note 1	Note 1.	\$ 2,389,467
CDBG-R Grant (approved 5/1/09 by City Council, but not yet funded)	- 9 by City Counci	  I, but not ye	t funded)					\$ 266,000		\$ 418,000		Note 1. \$ 684,000
Revised Uses		\$ 606,783		\$ 682,728	***	\$ 559,886		\$ 493,236	MARKY III	\$ 730,834	A STATE OF THE STA	\$ 3,073,467
July College								i de la companya de l				
		707/60 6		000,25 0		6/6/0/T ¢		(cc/'cgr) c		\$ (55°,425)		184,000T
The second secon	100 to an out of the second								A COLUMN TO A MANAGEMENT OF THE PROPERTY OF TH	V =/// /	Note 1: \$1,789,46	Note 1: \$1,789,467 amortizing, with
Debt Service after revisions to scopes of work and budgets:	copes of wark a	and budgets:						A			remaining loan b.	emaining loan balance res receipt
First priority/first lien	CCRC	175,481 Chase	Chase	587,641	Chase	124,237	Chase	237,825	Citibank	172,291	30 year amortizin	172,291 30 year amortizing loans, ave 7.63%
Second priority/third lien	SDRC rehab	606,783	SDRC rehab	682,728	SDRC rehab	559,886	SDRC rehab	227,236	SDRC rehab	312,834	312,834 3% 55 year amort res receipts cap	res receipts cap
Third priority/second lien	SDRC	236,557	N.A.		SDRC rehab	135,627	SDRC	220,000	SDRC	273,939	273,939 Modify third princity SDRC loans	ity SDRC loans
											residual receipts	residual receipts from 100% to 50%

9/16/2009 Revised 9/16/09

## Comprehensive Scopes of Work

<del> </del>	Alta Vista Apartments								
	The Court of the C								
		Original Bid	Deductions To	Contract Amount	Deduct Due To Addition of Energy	Energy Efficiency	Items To Add Back Into		Projected Final Contract
Spec#	Item Description	Amounts	Reach Contract	Executed 7/29/69	Efficiency Items	Items	Contract	Relocation	Amount
	Permits	2,006		2,070					2,07
R2	Debris Removal	4,782		4,934			***************************************		4,93
R3	Physical Disability Ramp	3,321		3,427					3,42
R4	Landings Replacement	37,719	(23,740)	13,979					13,97
R5	2nd Floor Landings and Deck Recoating	10,626		10,964					10,96
R6	Fiberglass Shingle Roof - New	39,313	(13,685)	25,628	(25,628)	33,471		(7,843)	25,62
R7	Aluminum Gutters, Remove and Replace	6,442		6,647					6,64
R8	New Stucco, Remove siding and install stucco	30,415	(26,440)	3,975					3,97
R9 R10	Exterior Painting	13,614		14,047					14,04
	Ext. Storage Room Doors	[2,59]		12,992				,	12,99
R11	Security Screen Doors	9,244							
R12 R13	Wood Fencing, Remove and Replace	10,187	(4,157)	6,030					6,03
R13	Stair Treads - Exterior R&R 14 treads	1,860 36,203	(489)	1,371					1,37
	Steel Stair Rails, Install new per code	l	(18,253)	17,950			18,253		36,20
	Irrigation System Upgrade. Install new	12,452	(6,456)	5,996					5,991
R16 R17	Tree/Shrub Planting	2,126 Deleter in		2,193			15,000	(15,000)	2,19
	Fire Extinguishers	Addendum 399		Deleted by add #1					1
	Mail Box Banks - Aluminum	970		412					41:
R20	High Pressure Sodium Flood Fixtures, R&R (18)		(73 ACA)	1,001	(2.000	4 322			1,00
R2 I	Parking Space Restripe	74,110 1,262	(72,054)	2,056 1,302	(2,056)	4,372			4,377
R22	Furnigation - Termites	1,262		1,302					1,30.
R23	Entry Doors, Remove and Replace	13,627	(10,749)	2,878					10,416
	Interior Doors, Remove and Replace	13,441	(9,823)	3,618					2,87
R25	Vinyl Windows,	24,863	(3,003)	25,655					3,61:
R26	Vinyl Sliding Glass Doors.	9,165		9,456					25,659 9,450
R27	Complete Interior Painting	23,110		23,846					23,844
R28	Carpeting - Complete	16,735		17,268	(17,268)	20,583		(3,315)	17,26
R29	Sheet Vinyl - Complete	14,026		14,472	(14,472)	28,152		(3,343)	28,152
	Window coverings: Window (52) & Door Blinds (12)	3,826		3,947	(213112)	20,132	······································		3,94
R31	Kitchen Cabinet Replacement	61,918		63,890	***************************************			,,, ,, ,,,, , , , , , , , , , , , ,	63,890
R32	Frost-free Refrigerator	12,910	(3,865)	9,045					9,04
R33	Electric Range	8,926	V-13-15-7	9,210					9,216
R34	Ductiess Range Hood Replacement	1,403		1,448					1,44
	Sliding Closet Doors , Remove and Replace	7,077		7,302					7,30
	Toilets. Remove and Replace with Low Flow	13,069		13,486				····	13,486
R37	Vanities, Remove and Replace	19,763	***************************************	20,393					20,395
R38	Tub Faucet Valve Replacements	17,266	(9,043)	8,223					8,22
	Tub/Shower Refinish	7,491		7,730					7,731
R40	Medicine Cabinets	1,945		2,007					2,007
	Bath Accessories - Sets	3,347		3,454		*****		······	3,454
	Bathroom Light/Vent Units	10,679	(3,441)	7,238	(7,238)	11,438			11,438
	ADA Bathroom Sink	1,064		1,098					1,098
	ADA Interior Doors	2,577		2,623					2,623
	R&R East Balconies per spec R4	23,195		23,934					23,934
R47	Water Heater subfloors. Remove and Replace	5,579		5,756		**			5,750
R48	Gable vents. Remove barriers	399		412					41:
R49	Packet door	4,084		4,215					4,21
R50	Wall Heaters. Remove and Replace	16,257		16,775					16,775
	GFI Outlets	2,869		2,961					2,96

							60,489		471,243
	TOTAL	671,903	(202,195)	471,243	(66,662)	120,056	33,253	(26,158)	531,732
N/A	Energy Star Water Heaters	399	-			17,000			17,000
N/A	Insulate Attics with R30 blown in					5,040			5,040
R53	Roof venting, Install new turbo vents	399		412					412
R52	Bath fan venting. Connect vents to roof	10,758		11,101					11,101

R1   1   R2   N3   N4   N5   N5   N5   N5   N5   N5   N5	Hem Description  Lead Remediation  Debris Removal  Permits  Vinyl Windows  Paint ext. trim  Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrai repair. Repair at #3431  Table cover repair and paint	Original Bid Amounts:  13,204  9,032  2,155  26,297  5,844  797  4,460  9,231  7,886  16,995  1,993  1,993  7,331  6,641  1,329  2,391	Deductions To Reach Contract	Contract Amount Executed 7/29/09  34,261  9,319  1,468  27,135  6,030  823  4,602  9,525  8,137  9,999  2,056  2,056  6,853  7,127	Deduct Due To Addition of Energy Efficiency Jiems	Energy Efficiency Items	from To Add BaskInto Contract	Add to Relocation	Projected Final Contract Amount  34,261  9,319  1,468  27,135  6,030  823  4,602  9,525  8,137  9,999  2,056  2,056
R1	Lead Remediation  Debris Removal  Permits  Vinyl Witedows  Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	Amounts  33,204  9,032  2,1,55  26,297  5,844  797  4,460  9,231  7,886  16,995  1,993  1,993  7,331  6,641  6,641  6,907  Detector by Attention 81  1,329	Reach Contract  (6,996)	Executed 7/29/09  34,261  9,319  1,468  27,135  6,030  823  4,602  9,525  8,137  9,999  2,056  2,056  7,556  6,853	Addition of Energy Efficiency Jiens	Items	BackInto		Amount  34,261  9,319  1,468  27,135  6,030  823  4,602  9,525  8,137  9,999  2,056
R1   1   R2   1   R3   1   R4   1   R5   1   R6   R7   R8   R9   R10   R11   R12   R13   R14   R15   R16   R17   C   R18   R19   R20   R21   R22   R22	Lead Remediation  Debris Removal  Permits  Vinyl Witedows  Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	Amounts  33,204  9,032  2,1,55  26,297  5,844  797  4,460  9,231  7,886  16,995  1,993  1,993  7,331  6,641  6,641  6,907  Detector by Attention 81  1,329	Reach Contract  (6,996)	Executed 7/29/09  34,261  9,319  1,468  27,135  6,030  823  4,602  9,525  8,137  9,999  2,056  2,056  7,556  6,853	Efficiency Jiems	Items			Amount  34,261  9,319  1,468  27,135  6,630  823  4,602  9,525  8,137  9,999  2,056
R1   1   R2   N3   N4   N5   N5   N5   N5   N5   N5   N5	Debris Removal  Permits  Vinyl Windows  Paint ext. trim  Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	9,032 2,155 26,297 5,844 797 4,460 9,231 7,886 16,995 1,993 1,993 7,331 6,641 Detector by Adding		9,319 1,468 27,135 6,030 823 4,602 9,525 8,137 9,999 2,056 2,056 7,556 6,853	(2,056)	36,220		(34,164)	9,319 1,468 27,135 6,930 823 4,602 9,525 8,137 9,999 2,056
R1	Permits  Vinyl Windows  Paint ext. trim  Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	2,155 26,297 5,844 797 4,460 9,231 7,886 16,995 1,993 1,993 7,331 6,641 Detector by Adding		1,468 27,135 6,030 823 4,602 9,525 8,137 9,999 2,056 2,056 7,556 6,853	(2,056)	36,220		(34,164)	1,468 27,135 6,030 823 4,602 9,525 8,137 9,999 2,056
R2	Vinyl Windows Paint ext. trim Paint ext. trim Steps/Jandings. R&R to ADA standards Accessibility Ramp Walkway/flatwork. Remove and Replace Parking Concrete. R&R 1370 s.f. Roof repair Roofing Laundry Rain Gutters. Remove and Replace Exterior Painting. Stucco only Security Doors. R&R (8) Exterior Door. R&R (2) Locksets. R&R (16) Deck repair. Replace 2x6 at #7 and #8 Guardrail repair. Repair at #3431 Table cover repair and paint	26,297 5,844 797 4,460 9,231 7,886 16,995 1,993 1,993 7,331 6,641 6,907 Detector by Attention 81 1,329		27,135 6,030 823 4,602 9,525 8,137 9,999 2,056 2,056 7,556	(2,056)	36,220		(34,164)	27,135 6,830 823 4,602 9,525 8,137 9,999 2,056
R3	Paint ext. trim  Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	5,844 797 4,460 9,231 7,886 16,995 1,993 1,993 7,331 6,644 Detector by Attom #1 1,329		6,030 823 4,602 9,525 8,137 9,999 2,056 2,056 7,556	(2,056)	36,220		(34,164)	6,030 823 4,602 9,525 8,137 9,999 2,056
R4   1   R5   S   S   R6   J   R7   S   S   R6   J   R7   S   R10   R11   R12   R13   S   R14   R15   R16   R17   C   R18   T   R18   T   R19   R20   J   R21   S   R22   S   R22   S   R22   S   R22   S   R22   S   R6   R6   R6   R6   R6   R6   R6	Paint ext. trim  Steps/Jandings. R&R to ADA standards  Accessibility Ramp  Walkway/Hatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roofi repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrai repair. Repair at #3431  Table cover repair and paint	797 4,460 9,231 7,886 16,995 1,993 1,993 7,331 6,644 Detector by Attom #1 1,329		823 4,602 9,525 8,137 9,999 2,056 2,056 7,556	(2,056)	36,220		(34,164)	823 4,602 9,525 8,137 9,999 2,056
R5	Steps/landings. R&R to ADA standards  Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardral repair. Repair at #3431  Table cover repair and paint	4,460 9,231 7,886 16,995 1,993 1,993 7,331 6,644 6,907 Deterted by Addin		4,602 9,525 8,137 9,999 2,056 2,056 7,556	(2,056)	36,220		(34, 264)	4,602 9,525 8,137 9,999 2,056
R6   R7   R8   J   R8   J   R10   J   R11   R12   R13   S   R14   J   R15   J   R16   J   R17   G   R18   R19   R20   J   R21   S   R22   S   R8   R8   R8   R8   R8   R8   R8	Accessibility Ramp  Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	9,231 7,886 16,995 1,993 1,993 7,331 6,641 6,907 Detetted by Adom #1 1,329		9,525 8,137 9,999 2,056 2,056 7,556 6,853	(2,056)	36,220		(34,164)	9,525 8,137 9,999 2,056
R7	Walkway/flatwork. Remove and Replace  Parking Concrete. R&R 1370 s.f.  Roofi repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardral repair. Repair at #3431  Table cover repair and paint	7,886 16,995 1,993 1,993 7,331 6,641 6,907 Detector by Adam #1		8,137 9,999 2,056 2,056 7,556 6,853	(2,656)	36,220		(34,164)	8,137 9,999 2,056
R8	Parking Concrete, R&R 1370 s.f.  Roof repair  Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Door. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardral repair. Repair at #3431  Table cover repair and paint	16,995 1,993 1,993 7,331 6,641 6,907 Detected by Adom fil		9,999 2,056 2,056 7,556 6,853	(2,056)	36,220		(34,164)	9,999 2,056
R10   R11   R12   R13   S   R14   R15   R16   R17   R18   R19   R20   R21   S   R22   R22	Roofing Laundry  Rain Gutters. Remove and Replace  Exterior Painting. Stucco only  Security Doors. R&R (8)  Exterior Doors. R&R (2)  Locksets. R&R (16)  Deck repair. Replace 2x6 at #7 and #8  Guardrail repair. Repair at #3431  Table cover repair and paint	1,993 7,331 6,641 6,907 Deleted by Addin #1		2,056 7,556 6,853	(2,056)	36,220		(34,164)	2,056
R11 1 R12 1 R13 5 R14 1 R15 1 R16 1 R17 0 R18 7 R19 1 R20 1 R21 5	Rain Gutters. Remove and Replace Exterior Painting. Stucco only Security Doors. R&R (8) Exterior Door. R&R (2) Locksets. R&R (16) Deck repair. Replace 2x6 at #7 and #8 Guardrail repair. Repair at #3431 Table cover repair and paint	7,331 6,644 6,907 Detected by Addin #1 1,329		7,556 6,853					2 056
R12   1   R13   S   R14   I   R15   I   R16   I   R17   G   R18   T   R19   R20   I   R21   S   R22   S	Exterior Painting, Stucco only  Security Doors, R&R (8)  Exterior Door, R&R (2)  Locksets, R&R (16)  Deck repair, Replace 2x6 at #7 and #8  Guardrail repair, Repair at #3431  Table cover repair and paint	6,641 6,907 Desented by Addim #1		6,853				···	
R13 S R14 I R15 I R16 I R17 G R18 R19 S R20 I R21 S	Security Doors, R&R (8)  Exterior Door, R&R (2)  Locksets, R&R (16)  Deck repair, Replace 2x6 at #7 and #8  Guardrai) repair, Repair at #3431  Table cover repair and paint	6,907 Deleted by Addin #1 1,329							7,556
R14 I R15 I R16 I R17 C R18 I R19 Y R20 I R21 S	Exterior Door, R&R (2) Locksets, R&R (16) Deck repair, Replace 2x6 at #7 and #8 Guardrai) repair, Repair at #3431 Table cover repair and paint	1,329		7177					6,853
R15 1 R16 1 R17 0 R18 7 R19 7 R20 1 R21 5	Locksets, R&R (16) Deck repair, Replace 2x6 at #7 and #8 Guardrai) repair, Repair at #3431 Table cover repair and paint	1,329					***************************************		7,127
R16 II R17 0 R18 7 R19 7 R20 II R21 5 R22 7	Deck repair, Replace 2x6 at #7 and #8 Guardrai) repair, Repair at #3431 Table cover repair and paint		1	Deleted by add #1		····	**************************************	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	()
R17 0 R18 7 R19 1 R20 1 R21 5 R22 7	Guardrail repair, Repair at #3431 Jable cover repair and paint	2,391		1,371					1,371
R18 7 R19 9 R20 J R21 5 R22	Table cover repair and paint	266	***************************************	2,467 275					2,467 275
R19 V R20 J R21 S R22 7		598		617			***************************************	//www.nr.es.	617
R21 5	Wood fencing, R&R at North and South sides	9,211		9,504					9,504
R22 1	Fence repairs. Repair on East side	233		240					240
	Steel fence repairs, R&R one 8' fence panel	1,222	(646)	576					576
R23	Tree/Stump removal. Remove (8) stumps on West side	2,126		2,193					2,193
1	Shrub trimming	319		329		•			329
	Water beaters. R&R (9)	20,766	(19,25%)	1,508	(1,50%)	18,630			18,630
	Service panel repairs. Install new covers and secure panels	I,100 Detected by Addin		1,100					1,100
	Flood Light Fixture, R&R (8)	#1	(1.451)	Deleted by add #1	(* 00h)	2.020			0
	Porch lights  Fan vent on ext wall	2,551 1,329	(1,454)	1,097 1,371	(1,097)	3,027			3,027 1,371
	Fumigation	7,571		7,812		***************************************	***************************************		7,812
	Wood replacement, R&R (2) window sills	930		960					960
	Playground	41,040	(41,040)	0					0
R32	Int. paint non-lead	11,688	***	12,060					12,060
R33 (	Carpeting	7,969		8,223	(8,223)	9,647		(1,424)	8,223
R34 5	Sheet vinyl	3,082		3,180	(3,180)	4,662			4,662
R35	Hardwood floor restoration XISS grains. Histail new grain and V-1 rap at all kitchens and	8,997	(5,091)	3,906			<del></del>		3,906
	baths	1,594		1,645					1,645
	Locksets interior. Install new lever hardware in (4) units	598		617					617
	Wall Furnace. Remove and Replace Smoke detectors	24,863 1,435	(11,049)	13,814					13,814 1,481
	Cabinet door, Replace doors at (2) units	1,433		2,056					2,056
	Counter tops see Addendum 1 R67	4,273		See R67					2,530
	Refrigerator	2,019		2,084					2,084
R43 (	Gas range	1,488		1,535					1,535
R44	Toilets. Remove and Replace with Low Flow	2,816	(458)	2,358					2,358
R45	Shower valve, Install (1) new in unit #2	1,262	(576)	686			··-		686
	Grab bars. Install new in unit #2	5()5		521					521
	Bath sink faucet. Install new in (4) units	1,382		1,426					1,426
	Shower doors. Install new all units	4,994		5,153					5,153
	Shower tile repair, Repair grout	1,063		1,097	`				1,097
<b></b>	Bath closer Sub panel, Install new subpanel at all units	412 26,882		425			100,000		100,000
	Duplex outlets Install one new outlet in all (16) units	4,720		4,720			100,000		4,720
	Switch/Outlet/Cover plates	0							0
	Bath Light/Vent	4;484	(2,291)	2,193	(2,193)	3,593			3,593
1	ADA Bath Sink	1,236		1,275		······ ··· · · · · · · · · · · · · · ·			1,275

Page 6 12:01 PM 9/17/2009

R56	ADA Doors (Pocket Doors)	2,856		2,920					2,920
	wan pass intough, Change myour in that #2 to show ADA	943		974					
	access								974
R58	Handrail. Install handrails at units 1,2	1,534		1,583					1,583
R59	Drain at sidewalk work. Add 3" drain	133		138					138
R60	Replaced damaged skylight	67		69					69
R61	New doors. Install (16) new entry doors	11,688		12,060					12,060
R62	Additional locks. Install (4) more locksets	638		658					658
R63	Clarification			0					0
R64	New High Pressure sodium fixtures (8)	4,423		4,564					4,564
R65	Add 5 units of Sheet vinyl	2,358		2,433					2,433
R66	Floor refinishing - Increase scope of work	9,463	(3,053)	6,410					6,410
R67	Kitchen Cabinet replacement	38,009		39,250					39,250
R68	Clarification on R31 - Allowance established								0
N/A	Insulate Attics, subfloors and walls					12,408			12,408
N/A	Upgrade Landscaping						15,000		15,000
	TOTAL	421,342	(318,794)	309,881	(18,257)	88,187	115,009	(35,588)	459,223
		······					149,342		309,881

Page 7 12:01 PM 9/17/2009

	Exclid Appetments	Stanovskie od openskie od							
Spec#	Item Description	Original Bid Amounts	Deductions To Reach Contract	Contract Amount Executed 7/29/09	Deduct Due To Addition of Energy Efficiency Items	Energy Efficiency Items	Items To Add Back Into Contract	Add to Relocation	Projected Final Contract Amount
Ahat	Lead Remediation	33,204		24.261					24.04
		7,020		34,261					34,26
	Ext. Storage/Laundry Room Doors  Entry Doors, Install (16) entry doors	14,153		7,243 14,604					7,24
	Replace all	35,196		36,317			·		14,60
	Kitchen Cabinet Replacement, R&R All	43,829		45,225					36,31 45,22
R5	Interior Doors, Remove and Replace	8,368		8,634				<del> </del>	8,63
R6	Vinyl Windows	1,528		1,576					1,57
R7	Exterior Painting	9,563		9,868					9,86
	Complete Interior Painting	21,915		22,613					22,61
	Permits	2,059		2,125			***************************************		2,12
	Debris Removal	2,922		3,015					3,01
RH	Tenant Accessibility Ramp	10,808		11,152					11,15
R12	Fiberglass Shingle Roofs - All 5 Bldgs	51,631		53,276		63,708		(10,432)	
R13	Aluminum Gotters - All 5 Bldgs Ke-rexture / Color Com. All (5) blogs. (5 MAU-Aspesius	10,426		10,758					10,75
	Removal)	46,485		47,966		5,000			52,96
R15	Security Screen Doors. R&R (16)	9,372	(8,767)	64)5					60
R16	Wood Fencing, R&R on South side	6,020	(808,E)	2,412					2,41
R17	Irrigation System Upgrade. Install new	12,432	(6,950)	5,482					5,48
R18	Tree/Shrub Planting, \$700 plant allowance	2,126		2,193		d between the Province of Command in Landson to the Province of the State of the St			2,19
R19	Water Heaters, R&R (12)	19,258	(11,035)	8,223	(8,223)	24,840			24,84
R20	Fire Extinguishers, R&R (4) Figh Pressure Sodium Frood Fixtures, Install [19] new	665		686					68
R21	fixtures	5,426	(2,137)	3,289	(3,289)	5,315			5,31.
R22	Furnigation - Termites	9,563		9,868			***************************************		9,86
R23	Carpeting - Complete	14,026		14,472	(14,472)	17,229		(2,757)	14,47.
R24	Sheet Vinyl - Complete	8,839		9,121	(9,123)	14,215			14,21
R25	Window Blinds (80)	4,251		4,386					4,38
	Frost-free Refrigerator	11,104	(2,662)	8,442					8,44
	Gas Range	8,182		8,420					8,42
	Ductless Range Hood Replacement	4,938		5,096					5,09
R29	Toilets. Remove and Replace with Low Flow	6,535	.,	6,743				<u> </u>	6,74
R30	Vanities	8,693		8,970					8,97
R31	Medicine Cabinets	2,646		2,730	1				2,73
	Bath Accessories - Sets	1,642	0.000	1,694	<u> </u>	£ 100			1,69
	Bathroom Light/Vent Units Gas Wall Furnace. R&R (12)	6,184	(2,894)	3,290	1	5,390	***************************************		5,39
	ADA Bathroom Sink	33,947 1,249	(13,308)	20,639 1,289				<del> </del>	20,63
	ADA Bannoom Sink  ADA Interior Doors - packet doors	2,776		2,865		<u> </u>		1	1,28
	Stucco Weep Screed. Install new weep screed	22,579	(16,754)	5,825	f				5,82
	Tankless water heater. Install new tankless unit	4,782	(1.5,1,7.7)	4,934	<u> </u>	***************************************			4,93
	Repair breken conduit	532		549					54
	Cabinet hardware repairs. Unit 4217 only	399		412					41
	Dishwasher, Unit 4217 only	399		412					41
R42	Tile repairs and replacement. Unit 4217 only	266		275	1				27
R43	Substrate substrate	1,729		1,809					1,80
N/A	Insulate Attics, subfloors and walls					13,820			13,82
N/A	Separate the electric and gas meters for units 17 and 17 1/2.						25,000	)	25,00
N/A	Mold remediation in two units per PNA	***************************************					9,000	)	9,00
	Rewire all electrical per PNA comments				-		60,000	)	60,00
	TOTAL	509,667	(68,115)	453,764	(91,671)	149,517	94,600	(13,189)	592,42
							138,657		453,764

Page 8 12:01 PM 9/17/2009

	San Diego Apartments		E 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				***************************************	<b>.</b>	
					Deduct Dac To		Items To Add	4 2 4 4	
Spec#	Item Description	Original Bid Amounts	Deductions To Reach Contract	Contract Amount Executed 7/29/09	Addition of Energy Efficiency Items	Energy Efficiency Items	Back Into Contract	Add to Relocation	Projected Final Contract Amount
RI	Permits	1,196		1,234					1,234
R2	Debris Removal	8,102	, , , , , , , , , , , , , , , , , , , ,	8,360					8,360
R3	Deck & Stairs - R&R at unit #16	21,062	(10,304)	10,758			10,304		21,062
R4	Fiberglass Shingle Roof - New	28,688		29,509		34,801		(5,292)	29,509
R5	Aluminum Gutters	5,379		5,551				<u> </u>	5,551
R6	Wood Siding - R&R all wood siding.	38,316		39,413					39,413
R7	Stucco Repairs. Minor repairs	1,594		1,645					1,645
R8	wood Broad Band - Keek wood Sking between 1st and 2nd floor	4,227		4,362					4,362
R9	Deck & Stair - Painting	2,989		3,084					3,084
R10	Exterior Metal Painting	1,612		1,612					1,612
R11	Exterior Storage Room Door	1,906		1,967					1,967
		13,021	(11,283)	1,783					1,783
	Tubular Steel Security Screen Door (4) units only ADA Compinant Exterior Door Handles, Install at all 1st floor units	2,823		2,913					2,913
R14	Wood & Steel Fencing, R&R at North side and S.E. corner	21,543	(7,838)	13,705					13,705
R15	Concrete Walkway	11,024	(1,0.75)	11,375					11,375
R16	Irrigation System Repair only	4,260	(1,519)	2,741					2,741
R17	Tree and Stump Removal at N.W. corner	1,461	(1/2/17)	1,508					1,508
R18	Water heaters. Remove and Replace (1)	9,032		9,319	(9,319)	15,859			1,300
R19		2,232				15,839			
R20	Flooring - Sheet Vinyl - R&R in water heater room  New ABS Drains in water heater room	1,461	***************************************	2,303					2,303
R21	Mail Box Bank (Enclosure)	333							1,508
R22	Electrical Service Shed Repair 24 sf of damage	350		343					343
R23				350				ļ	350
R24	High Pressure Sodium Flood Fixtures (8)	2,391		2,467	(2,467)	3,239			3,239
	Intercom Repairs	997	*****	1,028		<u> </u>			1,028
R25	Asphalt Driveway . Resurface	4,000		4,000					4,000
R26	Fumigation - Termites	7,969		8,223					8,223
R27	Entrance Door, R&R at unit #3	1,156		I,193					1,193
R28	Vinyl Windows	13,514		13,945					13,945
R29	Carpeting	8,766		9,045		10,792		(1,747)	9,045
R30	Flooring - Sheet Vinyl	2,790		2,878	(2,878)	4,728			4,728
R31	Clean/Adjust Furnace	2,126		2,193					2,193
R32	Thermostat. Install (12) New	3,188		3,290					3,290
R33	Replace Switch Cover/Outlet	140		144			[.	[-	544
R34	Kitchen Cabinet Replacement, Units #3 and #5	8,951		9,180					9,180
R35	Kitchen Countertop Replacement. Unit #13	1,559		1,604					1,604
	Frost-free Refrigerator. Units 5,13,14	3,985	(915)						3,070
R37	Electric Range. Units 5,13,14	2,162		2,224					2,224
R38	Ductless Range Hood Replacement. Units 5,13,14	249		257					257
R39	Colling Light Fixture -Units 9,11,14	1,116		1,152					1,152
	Battery Operated Smoke Detector, All units Security Onlie Refease - Repair quick refease at units	1,276		1,316					1,316
R41	5,9,15	997		1,028					1,028
R42	Toilets. Remove and Replace with Low Flow	4,516		4,660				<u> </u>	4,660
R43	Bathroom Vanity. Install new at (6) units	6,495		6,702				:	6,702
R44	Fibergiass Tub/Shower Unit. R&R in unit 8	9,005	(3,002)	6,003					6,003
R45 .	Bi-Pass Shower Door, Install new in units 3 and 5 Tuo Faucer vaives Replacements, Install new in units	1209		1248					1,248
	3,7,14	2790	(1,487)	1303					1,303
R47	Bathroom Vent Units, Install new in units 13,14	797	(208)	589	(589)	939			939
R48	Pocket Door, Unit 15 only	2922		3001					3,001
R49	ADA Door Locksets. R&R at (8) units	893		921					921
R50	ADA Faucet. R&R at (8) units	5512		5701					5,701
N/A	Insulate attics with blown in insulation					3384			3,384
N/A	Upgrade Landscaping						15,000		15,000
	TOTAL	284,082	(36,556)	253,798	(53,807)	73,742	25,304	(7,039)	291,908
							38,200		253,708

Page 9 12:01 PM 9/17/2009

arine and an	Fersitz Apartments			Footonia and a second		Bankan and an ann an			
		Original Bid	Deductions I'u	Contract Amount	Deduct Due To Addition of Energy	Energy Efficiency	items To Add Back Into		Projected Final Contract
Spec#	Item Description	Amounts	Reach Contract		Efficiency Items	Items	Contract	Add to Relocation	Amount
RI	Permits	2,341		2,416					2,416
R2	Debris Removal	3,852		3,975					3,975
R3	Tenant Accessibility Ramp at unit 2	1,860		1,919			·		1,919
R4	Deck Recoating Recoat landings on both buildings	7,969		8,223				· · ·	8,223
R5	Fiberglass Shingle Roof - New	47,813		49,336	(69,336)	59,332		(9,996)	49,336
R6	Aluminum Gutters	9,629		9,936					9,936
R7 R8	Exterior Painting  Ext. Storage Room Doors	14,477		14,938 13,294					14,938
R9	Security Screen Doors, R&R (13)	7,511	(6,174)	1,337					13,294 1,337
R10	Wood Fencing, Install 220 If new wood fence	9,563	(0,174)	9,868			***	***************************************	9,868
	Stair Treads - Exterior, R&R (20)	2,657	(1,971)	686					5,800
R12	Steel Stair Rails, Install new per code	27,626	(14,469)	13,157			14,469		27,626
ļ,	Irrigation System Upgrade. Install New	10,639	(6,239)	4,400			5,000		9,400
R14	Tree/Shrub Planting, \$700 plant allowance	_		0			10,000	(5,000)	
R15	Install New Water Heaters, R&R (6)	Deleted by Andm #1		Deleted by add #1			***************************************		0
R16	Fire Extinguishers, R&R (4)	480		480					480
R17	Mail Box Banks	1,169		1,206					1,206
R18	High Pressure Sodium Flood Fixtures. R&R (18)	5,021	(1,320)	3,701	(3,701)	5,727			5,727
R19	Parking Space Restripe	598		617					617
R20	Fumigation - Termites	12,817		13,225					13,225
R21	Metal Garage Doors. R&R (8)	5,101	(4,004)	1,097					1,097
R22	Playground Equipment/Safety Surface	41,549	(41,549)				15,000		15,000
R23	Intercom Panels	1,329		1,371					1,371
R24	Entry Doors and jambs. R&R (13)	17,957	(11,721)	6,236					6,236
R25	Interior Doors, R&R (48)	14,026	10,408	3,618					3,618
R26	Vinyl Sliding Glass Doors, R&R (8)	6,110	***************************************	6,304					6,304
R27	Complete Interior Painting	25,036		25,833					25,833
R28	Carpeting - Complete	25,899		26,724	(26,724)	30,577		(3,853)	26,724
R29	Sheet Vinyl & base - Complete	11,655		12,026	(12,026)	21,872			21,872
R30	Window (52) & Door Blinds (10)	3,826	***************************************	3,947			······································		3,947
R31	Kitchen Cabinet Replacement- Complete	60,629		62,561				***************************************	62,561
	Frost-free Refrigerator. R&R (13)	13,059	(5,351)	7,708					7,708
R33 R34	Electric Range. R&R (13)	9,605	(2,951)	6,654			***************************************		6,654
	Ductless Range Hood Replacement, R&R (13)  Sliding Closet Doors - Sets	1,456		1,489			***************************************		1,489
R36	Toilets. Remove and Replace with Low Flow	11,834		12,211					5,126
R37	Vanities- Complete	17,516		18,074				······	12,211
R38	Tub Faucet Valve Replacements. R&R (22)	18,847	(11,369)	7,538					7,538
R39	Tub/Shower Refinish- (22) locations	8,115	(2,318)	5,797					5,797
R40	Medicine Cabinets	1,929	199-1467	1,990					1,990
R41	Bath Accessories - Sets	3,068	. ,	3,166					3,166
R42	Bathroom Light/Vent Units	11,980	(5,950)	6,030	(6,030)	3,850			3,850
R43	ADA Bathroom Sink Unit 2	1,986		2,049					2,049
R44	ADA Interior Doors. Unit 2	2,070		2,115					2,115
R45	Remove and reinstall solar system for roofer	4649		4,797					4,797
R46	Hoxe bid	422		460					460
N/A	Insulate attics with blown in insulation					6408			6,408
<u> </u> 	TOTAL	593,526	(194,918)	387,635	(97.817)	127,766	44,469	(18,849)	443,294
							55,569		387,635
	Tark To APP.	2,390,520		1.007.444	-2766 AV 20	050.046	250 100	2060 BAN	
	Totals For All Projects	2,390,220	(530,578)	1,876,231	(378,214)	\$59,268	312,026	(100,823)	2,318,488
							Totals:	442,257	442,257
L									
						A STATE OF THE STA			